

Cover sheet for PPA report					
		Organization	DURMETAL IND E COM PEÇAS E MÁQ. LTDA-EPP		
Organization			Reason for report generation		
DURMETAL IND E COM PEÇAS E MÁQ. LTDA-EPP AVENIDA SANTOS DUMONT, 3939 BR - 89219730 JOINVILLE			X	Report on production process and product approval (PPA)	
				Report on other samples	
				Requalification	
			Trigger of PPA procedure		
				Sample presentation	
Customer (Recipient)			New part		
Bosch Rexroth R. Luiz Abry, 2225 - Ribeirão Areia BR - Pomerode				Changes to product	
			X	Changes to production process	
				Change to supply chain	
				Re-use > 12 months standstill	
				Updated PPA documentation	
Details of the organization		Details of samples		Details of the customer	
Report no.		Delivery no.		Customer	BOSCH-PoP
Report version	0	Delivery quantity		Ordering no. PPF example	
Delivery location		Charge no.		Unloading point	
Production location		Example weight [kg]		Part no.	1515500302
Part no.	1515500302	Hardware version		Name	TAMPA
Name	TAMPA	Diagnosis status		Drawing no.	1515500038
Drawing no.		Software version		Version / Date	16 / 04.12.2006
Version / Date	/	Identification / DUNS	/ 908487887	Software approval	
Organization confirmation It is hereby confirmed that the PPF process has been carried out in accordance with the agreements of the sampling coordination and according to the specifications of VDA Volume 2.					
The IMDS record was created under the MDB-ID no.:					
Organization confirmation					
Name		Comment			
Department					
Telephone					
Email / Fax-No.	/				
Date		Signature			
Decision customer					
Customer-ready/Ready for series production			Not customer-ready / Not ready for series production		
PPA procedure towards customer closed			New PPA procedure required		
Update of PPA documentation required					
Report no. / version Customer		DC-20325 / 0			
Name	Wolter, Larissa	Comment			
Department	DC/PUE-Po				
Telephone	+55(47)3387-9399				
Email / Fax-No.	Larissa.Wolter@boschrexroth.com.br /				
Date		Signature			

PPAP para validar a retomada de fornecimento + alteração de processo (mudança de torno na OP10) das tampas zincadas, variantes do fundido 1515500013

Part numbers contemplados:

1515500302
1515500038